

Incident: 53697 ▼[Options](#) ▼[Print](#)[Refresh](#)

Status: Complete

Short Description: Vent condensor fumes/vapor dripping

Responsible Department: Peru Plant : Utilities-Peru

Level of Consequence: INCIDENT

Subtypes

Incident Sub Types: General: Health & Safety

General

Supervisor: PLOCH, RICHARD

Location: Tank Farm

Date Occurred: 9/19/2011 12:00 AM

Date Reported: 9/19/2011 1:59 PM

Summary of Incident: Night Guard, while on his rounds, notified Supervisor of the strong smell of Styrene in the Utilities area. Mid-West/Riverdock was pumping off Barge KIRBY 18026 to tank #3. Supervisor found that the vent condensor fumes/vapor was dripping on top of the tank & a small amount had run down the Northwest side of the tank. Informed Tanker Ops. to stop transfer of product. Placed spill pads under area. Contacted Steve E. About one-half quart of material was found. Checked Vent Condensor & both were found to be on & running as required, valves were open. Had Tanker Ops. slow down transfer of product so vent unit can better keep up with transfer. Guard & Supervisor will monitor tank for duration of pump. Utilities Ops. will clean up spill pads in a.m.

Legal Hold?: N

Responsibilities

Supervisor: EMMETT, STEVEN